North America Emission Control Area Fuel Oil Non-Availability Report ## ECA0100

ECA Fuel Oil Non-Availability Report

Report From ID : ECA0100 field No.

Field Name

Report Form ID

Ship Operator Name

Vessel Name

Flag Country

IMO ID Number

Date of ECA First Notice

Location of ECA First Notice

Name of Ports after First Notice

Name of Last Port before ECA Entry

Name of Port with Fuel Oil Supply Disruption

Name of Original Fuel Supplier with Disruption

Number of Fuel Suppliers Contacted

Date of Entry in the ECA

Time of Entry in the ECA

Sulfur Content of Non-Compliant Fuel Oil

Projected Hours on Main Propulsion

Name of First POC

Compliance Fuel Oil Available at First POC?

Plan to Bunker Compliant Fuel Oil at First POC?

Number of fuel suppliers contacted at First POC

Name of Second POC

Compliant Fuel Oil at Second POC?

Plan to Bunker Compliance Fuel Oil at Second POC?

Number of Fuel Suppliers Contacted at the Second POC?

Date of Exit from ECA?

Time of Exit from ECA?

Has this vessel operated in the ECA in previous 12 months?

Number of Separate Visits to the ECA

Number of Ports visited in the ECA

Previously submitted ECA0100 forms?

Number of Submitted Reports


Designated Corporate Official Name

Designated Corporate Official E-mail

Designated Corporate Official Phone Number

Description of Actions to Achieve Compliance

Units



Hanjin Shipping Co.,LTD Hanjin Lisbon DE 9248148 19TH JUL. 2013 Shanghai anchorage Ningbo Ningbo Ningbo World Fuel Service, Bright Oil, KTB Oil 3 06TH AUG. 2013 0100 UTC 3.48 30 LONG BEACH Υ γ NA NA NA NA NA 12TH AUG. 2013 0900 LT Ν NA NA Υ 2 Ryu Jeung-UK juryu@hanjin.com 82-51-460-8195 Original Vessel that service this Voyage was M/V Hanjin Copenhagen. But, Some Damage were found on M/V Hanjin Copenhagen. So, we changed the Vessel from M/V Hanjin Copenhagen to M/V Hanjin Lisbon. Unfortunately, M/V Hanjin Lisbon's next service was Inter Asia port, so she didn't have LSFO. We tried to arrange the LSFO at Ningbo where her first service port. We contacted 3 suppliers and got the answer that they could not supply the LSFO at this port.

Field Formats, Codes, & Special Instructions

ECA0100

Her next port after Ningbo is Long beach.

Therefore, we arrange the LSFO at Long beach as the best way.

North America Emission Control Area Fuel Oil Non-Availability Report ## ECA0100

ECA Fuel Oil Non-Availability Report

Report From ID : ECA0100 field No.

Field Name Units Field Formats, Codes, & Special Instructions

Report Form ID ECA0100

Ship Operator Name Hanjin Shipping Co.,LTD

Vessel Name Hanjin Lisbon

Flag Country DE

IMO ID Number 9248148

Date of ECA First Notice 19TH JUL. 2013
Location of ECA First Notice Shanghai anchorage

Name of Ports after First Notice Long Beach
Name of Last Port before ECA Entry Ningho

Name of Last Port before ECA Entry

Ningbo

Name of Port with Fuel Oil Supply Disruption

Name of Original Fuel Supplier with Disruption
Number of Fuel Suppliers Contacted

Date of Entry in the ECA 06TH AUG. 2013

Time of Entry in the ECA 0100 UTC

Sulfur Content of Non-Compliant Fuel Oil

Projected Hours on Main Propulsion

Compliance Fuel Oil Available at First POC?

Plan to Bunker Compliant Fuel Oil at First POC?

Number of fuel suppliers contacted at First POC

Name of Second POC

Name of First POC

Compliant Fuel Oil at Second POC?

Plan to Bunker Compliance Fuel Oil at Second POC? Number of Fuel Suppliers Contacted at the Second POC?

Date of Exit from ECA? 12TH AUG. 2013

Time of Exit from ECA? 0200 UTC

Has this vessel operated in the ECA in previous 12 months?

Number of Separate Visits to the ECA

Number of Ports visited in the ECA

Previously submitted ECA0100 forms?

Number of Submitted Reports

Designated Corporate Official Name

Designated Corporate Official E-mail

Designated Corporate Official Phone Number

Description of Actions to Achieve Compliance